

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- | | |
|--|---|
| <p>1. Name of the Officer</p> <p>2. Name of the School</p> <p>3. Location with name of Education District/ Sub. District</p> <p>4. Period for which the certificate is</p> <p>5. Classification of Building as specified in column 4 of the application for fitness certificate and size</p> | <p>Haseena N K</p> <p>YAMANIYA ENGLISH MEDIUM SCHOOL,
POOKOTUMPADAM
Wandoor ED / Nilambur SubDist.</p> <p>2021-2022</p> |
|--|---|
-
- | | | |
|--|--------------|---|
| <p>6. Nature of defects , if any</p> <p>a) Foundation and basement.</p> <p>b) Superstructure</p> <p>c) Doors and Windows</p> <p>d) Wood work wrought and put up.</p> <p>e) Roof.</p> <p>f) Flooring</p> <p>g) Miscellaneous (Cracks, etc.)</p> | <p>→ Nil</p> | <p>Block I</p> <p>Permanent RCC roof 3 storied GF - 1x31x6.20x3.60m (4class room)</p> <p>" " FF - 1x31x6.20x3.60m (4class room)</p> <p>" 2nd floor - 1x31x6.20x3.60m (4class room)</p> <p>Block II</p> <p>Semi Permanent single storied GF - 1x35x6.00x3.60m (5class room)</p> <p>Block III</p> <p>Permanent RCC roof 3 storied GF - 1x41x6.20x3.60m (6class room)</p> <p>" " FF - 1x41x6.20x3.60m (6class room)</p> <p>" 2nd floor - 1x41x6.20x3.60m (6class room)</p> <p>Block IV</p> <p>Permanent RCC roof 4 storied GF - 1x22x6.20x3.60m (3class room)</p> <p>" " FF - 1x22x6.20x3.60m (3class room)</p> <p>" 2nd floor - 1x22x6.20x3.60m (3class room)</p> <p>" 3rd floor - 1x22x6.20x3.60m (3class room)</p> <p style="text-align: right;">Total class rooms = 47 nos</p> |
|--|--------------|---|
-
- | | |
|--|---|
| <p>7. Any major defects noticed which will render the building unsafe in any manner</p> <p>8. Whether maintenance works have been done properly</p> <p>9. Whether the structure is sound or not for conducting classes</p> | <p>Nil</p> <p>Yes</p> <p>Yes. Fit for conducting classes under normal weather conditions as far as could be seen externally</p> |
|--|---|

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 05/07/2021 and found to be fit to conduct classes, for the period 2021-2022 for the reasons stated above.

Place : POOKKOTTUMPADAM

Date : 05/07/2021



[Signature]

Haseena NK

Assistant Engineer, L.S.G.D. Section
Amarambalam Grama Panchayat
PO Pookkottumpadam 679332